

# *Chapter 7*

## *Attributes Control Charts*

### *Control Charts for Attributes*

- *Many quality characteristics cannot be conveniently represented numerically.*
- *Quality characteristics of this type are called attributes; for examples:*
  - *the proportion of warped automobile engine connecting rods in a day's production*
  - *the number of nonfunctional semiconductor chips on a wafer*
  - *the number of errors or mistakes made in completing a loan application*
  - *the number of medical errors made in a hospital*

## *Control Charts for Attributes*

- *We usually classify each item inspected as either conforming or nonconforming to the specifications on that quality characteristic*
- *The terminology **defective** or **non-defective**, and **conforming** or **nonconforming**, used to identify these two classifications of product*
- *We will discuss three widely used attributes control charts:*
  - *Control chart for fraction nonconforming, or **p chart***
  - *Control chart for nonconformities, or the **c chart***
  - *Control chart for nonconformities per unit, or the **u chart***

## *Control Chart for Fraction Nonconforming*

- *The **fraction nonconforming** is defined as the ratio of the number of nonconforming items in a population to the total number of items in that population.*
- *The items may have several quality characteristics that are examined simultaneously by the inspector.*
- *If the item does not conform to standard on one or more of these characteristics, it is classified as nonconforming.*
- *The statistical principles underlying the control chart for fraction nonconforming are based on the **binomial distribution**.*

## Control Chart for Fraction Nonconforming

- Suppose the production process is operating in a stable manner, such that the probability that any unit will not conform to specifications is  $p$ ,
- Also, the successive units produced are **independent**.
- Then each unit produced is a realization of a **Bernoulli random variable** with parameter  $p$ .
- If a random sample of  $n$  units of product is selected, and if  $D$  is the number of units of product that are **nonconforming**, then  $D$  has a **binomial distribution** with parameters  $n$  and  $p$ ; that is,

$$P\{D = x\} = \binom{n}{x} p^x (1-p)^{n-x} \quad x = 0, 1, \dots, n$$

## Control Chart for Fraction Nonconforming

- The **sample fraction nonconforming** is defined as the ratio of the number of nonconforming units in the sample  $D$  to the sample size  $n$ —that is,

$$\hat{p} = \frac{D}{n}$$

- It has binomial distribution, with the mean and variance of:

$$\mu_{\hat{p}} = p$$

$$\sigma_{\hat{p}}^2 = \frac{p(1-p)}{n}$$

## *p* chart (Fraction Nonconforming)

- If  $w$  is a statistic that measures a quality characteristic, and if the mean of  $w$  is  $\mu_w$  and the variance of  $w$  is  $\sigma_w^2$ , then the general model for the Shewhart control chart is as follows:

$$\begin{aligned} \text{UCL} &= \mu_w + L\sigma_w \\ \text{Center line} &= \mu_w \\ \text{LCL} &= \mu_w - L\sigma_w \end{aligned}$$

- where  $L$  is the distance of the control limits from the center line, in multiples of the standard deviation of  $w$ .
- It is customary to choose  $L = 3$

## *p* chart (Fraction Nonconforming)

- Suppose that the true fraction nonconforming  $p$  in the production process is known or is a specified **standard value**.

### Fraction Nonconforming Control Chart: Standard Given

$$\begin{aligned} \text{UCL} &= p + 3\sqrt{\frac{p(1-p)}{n}} \\ \text{Center line} &= p \\ \text{LCL} &= p - 3\sqrt{\frac{p(1-p)}{n}} \end{aligned} \tag{7.6}$$

## *p* chart (Fraction Nonconforming)

- When the process fraction nonconforming  $p$  is **not known**,
- So, select  $m$  preliminary samples, each of size  $n$ , as a general rule,  $m$  should be at least 20 or 25, and  $n$  should be 4 to 6
- Then if there are  $D_i$  nonconforming units in sample  $i$ , we compute the fraction nonconforming in the  $i^{\text{th}}$  sample as

$$\hat{p}_i = \frac{D_i}{n} \quad i = 1, 2, \dots, m$$

- and the average of these individual sample fractions nonconforming is

$$\bar{p} = \frac{\sum_{i=1}^m D_i}{mn} = \frac{\sum_{i=1}^m \hat{p}_i}{m}$$

## *p* chart (Fraction Nonconforming)

- The statistic  $\bar{p}$  estimates the unknown fraction nonconforming  $p$ .
- The center line and control limits of the control chart for fraction nonconforming are computed as follows:

### Fraction Nonconforming Control Chart: No Standard Given

$$\begin{aligned} \text{UCL} &= \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}} \\ \text{Center line} &= \bar{p} \\ \text{LCL} &= \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}} \end{aligned} \quad (7.8)$$

## *p* chart (Fraction Nonconforming)

- *Example 7.1* Frozen orange juice concentrate is packed in 6-oz cardboard cans. These cans are formed on a machine by spinning them from cardboard stock and attaching a metal bottom panel.
- By inspection of a can, we may determine whether, when filled, it could possibly leak either on the side seam or around the bottom joint. Such a nonconforming can has an improper seal on either the side seam or the bottom panel.
- Set up a control chart to improve the fraction of nonconforming cans produced by this machine

## *p* chart (Fraction Nonconforming)

■ **TABLE 7.1**

Data for Trial Control Limits, Example 7.1, Sample Size  $n = 50$

Sample Number	Number of Nonconforming Cans, $D_i$	Sample Fraction Nonconforming, $\hat{p}_i$	Sample Number	Number of Nonconforming Cans, $D_i$	Sample Fraction Nonconforming, $\hat{p}_i$
1	12	0.24	17	10	0.20
2	15	0.30	18	5	0.10
3	8	0.16	19	13	0.26
4	10	0.20	20	11	0.22
5	4	0.08	21	20	0.40
6	7	0.14	22	18	0.36
7	16	0.32	23	24	0.48
8	9	0.18	24	15	0.30
9	14	0.28	25	9	0.18
10	10	0.20	26	12	0.24
11	5	0.10	27	7	0.14
12	6	0.12	28	13	0.26
13	17	0.34	29	9	0.18
14	12	0.24	30	6	0.12
15	22	0.44		347	$\bar{p} = 0.2313$
16	8	0.16			

## *p chart (Fraction Nonconforming)*

- Answer: to establish the control chart
- $m = 30$  samples of  $n = 50$  cans

$$\bar{p} = \frac{\sum_{i=1}^m D_i}{mn} = \frac{347}{(30)(50)} = 0.2313$$


$$\begin{aligned}\bar{p} \pm 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}} &= 0.2313 \pm 3\sqrt{\frac{0.2313(0.7687)}{50}} \\ &= 0.2313 \pm 3(0.0596) \\ &= 0.2313 \pm 0.1789\end{aligned}$$

$$UCL = \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}} = 0.2313 + 0.1789 = 0.4102$$

$$LCL = \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}} = 0.2313 - 0.1789 = 0.0524$$

## *p chart (Fraction Nonconforming)*

- Answer:
- Out of control chart!




## *p* chart (Fraction Nonconforming)

- Answer:
- In control chart!

$$\bar{p} = \frac{301}{(28)(50)} = 0.2150$$

$$UCL = 0.2150 + 3\sqrt{\frac{0.2150(0.7850)}{50}} = 0.3893$$

$$LCL = 0.2150 - 3\sqrt{\frac{0.2150(0.7850)}{50}} = 0.0407$$



## *p* chart (Fraction Nonconforming)

- Selection of sample size in a critical question in these charts
- Duncan (1986) has suggested that the sample size should be large enough that we have approximately a 50% chance of detecting a process shift of some specified amount.
- If  $\delta$  is the magnitude of the process shift, then  $n$  must satisfy  $\delta = L\sqrt{\frac{p(1-p)}{n}}$

$$n = \left(\frac{L}{\delta}\right)^2 p(1-p)$$

## *p chart (Fraction Nonconforming)*

- For example, suppose that  $p = 0.01$ , and we want the probability of detecting a shift to  $p = 0.05$  to be 0.50.
- Then,  $p = 0.01$ ,  $\delta = 0.05 - 0.01 = 0.04$ , and if three-sigma limits are used, we have:

$$n = \left( \frac{L}{\delta} \right)^2 p(1-p)$$

$$n = \left( \frac{3}{0.04} \right)^2 (0.01)(0.99) = 56$$

## *p chart (Fraction Nonconforming)*

- If the in-control value of the fraction nonconforming is **small**, another useful criterion is to choose  $n$  **large** enough so that the control chart will have a positive lower control limit.
- Since we wish to have

$$\text{LCL} = p - L \sqrt{\frac{p(1-p)}{n}} > 0$$

- This implies that

$$n > \frac{(1-p)}{p} L^2$$

## *p* chart (Fraction Nonconforming)

- For example, if  $p = 0.05$  and three-sigma limits are used, the sample size must be

$$n > \frac{(1-p)}{p} L^2$$

$$n > \frac{0.95}{0.05} (3)^2 = 171$$

- Thus, if  $n \geq 172$  units, the control chart will have a positive lower control limit.

## *np* chart (Number Nonconforming)

- It is also possible to base a control chart on the **number nonconforming** rather than the fraction nonconforming. This is often called a **number nonconforming (np) control chart**. The parameters of this chart are as follows.

### The *np* Control Chart

$$\begin{aligned} \text{UCL} &= np + 3\sqrt{np(1-p)} \\ \text{Center line} &= np \\ \text{LCL} &= np - 3\sqrt{np(1-p)} \end{aligned} \quad (7.13)$$

- ☛ If a standard value for  $p$  is unavailable, then  $\bar{p}$  can be used to estimate  $p$ .

## *Variable Sample Size*

- *In some applications of the control chart for fraction nonconforming, the sample is a 100% inspection of process output over some period of time.*
- *Since different numbers of units could be produced in each period, the control chart would then have a variable sample size.*
- *There are three approaches to constructing and operating a control chart with a variable sample size:*
  - *Variable-Width Control Limits*
  - *Control Limits Based on an Average Sample Size*
  - *The Standardized Control Chart*

## *Variable-Width Control Limits*

- *That is, if the  $i^{\text{th}}$  sample is of size  $n_i$ , then the upper and lower control limits are*

$$\bar{p} \pm 3\sqrt{\bar{p}(1 - \bar{p})/n_i}$$

- *Note that the width of the control limits is inversely proportional to the square root of the sample size*
- *For example, consider the data in Table 7.4*

■ TABLE 7.4

Purchase Order Data for a Control Chart for Fraction Nonconforming with Variable Sample Size

Sample Number, $i$	Sample Size, $n_i$	Number of Nonconforming Units, $D_i$	Sample Fraction Nonconforming, $\hat{p}_i = D_i/n_i$	Standard Deviation $\hat{\sigma}_{\hat{p}} = \sqrt{\frac{(0.096)(0.904)}{n_i}}$	Control Limits	
					LCL	UCL
1	100	12	0.120	0.029	0.009	0.183
2	80	8	0.100	0.033	0	0.195
3	80	6	0.075	0.033	0	0.195
4	100	9	0.090	0.029	0.009	0.183
5	110	10	0.091	0.028	0.012	0.180
6	110	12	0.109	0.028	0.012	0.180
7	100	11	0.110	0.029	0.009	0.183
8	100	16	0.160	0.029	0.009	0.183
9	90	10	0.110	0.031	0.003	0.189
10	90	6	0.067	0.031	0.003	0.189
11	110	20	0.182	0.028	0.012	0.180
12	120	15	0.125	0.027	0.015	0.177
13	120	9	0.075	0.027	0.015	0.177
14	120	8	0.067	0.027	0.015	0.177
15	110	6	0.055	0.028	0.012	0.180
16	80	8	0.100	0.033	0	0.195
17	80	10	0.125	0.033	0	0.195
18	80	7	0.088	0.033	0	0.195
19	90	5	0.056	0.031	0.003	0.189
20	100	8	0.080	0.029	0.009	0.183
21	100	5	0.050	0.029	0.009	0.183
22	100	8	0.080	0.029	0.009	0.183
23	100	10	0.100	0.029	0.009	0.183
24	90	6	0.067	0.031	0.003	0.189
25	90	9	0.100	0.031	0.003	0.189
2,450		234	2.383			

## Variable-Width Control Limits


- Answer: For the 25 samples, we calculate

$$\bar{p} = \frac{\sum_{i=1}^{25} D_i}{\sum_{i=1}^{25} n_i} = \frac{234}{2,450} = 0.096$$

- Consequently, the center line is at 0.096, and the control limits are

$$UCL = \bar{p} + 3\hat{\sigma}_{\hat{p}} = 0.096 + 3\sqrt{\frac{(0.096)(0.904)}{n_i}}$$

$$LCL = \bar{p} - 3\hat{\sigma}_{\hat{p}} = 0.096 - 3\sqrt{\frac{(0.096)(0.904)}{n_i}}$$



## Control Limits Based on an Average Sample Size

- The second approach is to base the control chart on an average sample size, resulting in an **approximate set of control limits**.
- For the purchase order data in Table 7.4, we find that the average sample size is


$$\bar{n} = \frac{\sum_{i=1}^{25} n_i}{25} = \frac{2,450}{25} = 98$$

## Control Limits Based on an Average Sample Size

- Therefore, the approximate control limits are

$$UCL = \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{\bar{n}}} = 0.096 + 3\sqrt{\frac{(0.096)(0.904)}{98}} = 0.185$$

$$LCL = \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{\bar{n}}} = 0.096 - 3\sqrt{\frac{(0.096)(0.904)}{98}} = 0.007$$




## The Standardized Control Chart

- The third approach to dealing with variable sample size is to use a standardized control chart, where the points are plotted in standard deviation units.
- Such a control chart has **the center line at zero**, and **upper and lower control limits of +3 and -3**, respectively.
- The variable plotted on the chart is

$$Z_i = \frac{\hat{p}_i - p}{\sqrt{\frac{p(1-p)}{n_i}}} \quad (7.14)$$

## The Standardized Control Chart

- The standardized control chart for the purchase order data in Table 7.4 is:



■ TABLE 7.5

Calculations for the Standardized Control Chart in Figure 7.9,  $\hat{p} = 0.096$ 

Sample Number, $i$	Sample Size, $n_i$	Number of Nonconforming Units, $D_i$	Sample Fraction Nonconforming, $\hat{p}_i = D_i/n_i$	Standard Deviation $\hat{\sigma}_p = \sqrt{\frac{(0.096)(0.904)}{n_i}}$	$z_i = \frac{\hat{p}_i - \bar{p}}{\sqrt{\frac{(0.096)(0.904)}{n_i}}}$
1	100	12	0.120	0.029	0.83
2	80	8	0.100	0.033	0.12
3	80	6	0.075	0.033	-0.64
4	100	9	0.090	0.029	-0.21
5	110	10	0.091	0.028	-0.18
6	110	12	0.109	0.028	0.46
7	100	11	0.110	0.029	0.48
8	100	16	0.160	0.029	2.21
9	90	10	0.110	0.031	0.45
10	90	6	0.067	0.031	-0.94
11	110	20	0.182	0.028	3.07
12	120	15	0.125	0.027	1.07
13	120	9	0.075	0.027	-0.78
14	120	8	0.067	0.027	-1.07
15	110	6	0.055	0.028	-1.46
16	80	8	0.100	0.033	0.12
17	80	10	0.125	0.033	0.88
18	80	7	0.088	0.033	-0.24
19	90	5	0.056	0.031	-1.29
20	100	8	0.080	0.029	-0.55
21	100	5	0.050	0.029	-1.59
22	100	8	0.080	0.029	-0.55
23	100	10	0.100	0.029	0.14
24	90	6	0.067	0.031	-0.94
25	90	9	0.100	0.031	0.13

## OC Function in $p$ chart

- The operating-characteristic (or OC) function of the fraction nonconforming control chart is a graphical display of the probability of incorrectly accepting the hypothesis of statistical control (i.e., a type II or  $b$ -error) against the process fraction nonconforming

$$\begin{aligned}
 \beta &= P\{\hat{p} < \text{UCL}|p\} - P\{\hat{p} \leq \text{LCL}|p\} \\
 &= P\{D < n\text{UCL}|p\} - P\{D \leq n\text{LCL}|p\}
 \end{aligned}
 \tag{7.15}$$

## *Average Run Lengths (ARLs) in p chart*

$$ARL = \frac{1}{P(\text{sample point plots out of control})}$$

$$ARL_0 = \frac{1}{\alpha}$$

$$ARL_1 = \frac{1}{1 - \beta}$$

## *Control Charts for Nonconformities (Defects)*

- *A nonconforming item is a unit of product that does not satisfy one or more of the specifications for that product*
- *Consequently, a nonconforming item will contain at least one nonconformity*
- *Depending on their nature and severity, it is quite possible for a unit to contain several nonconformities and **not** be classified as nonconforming*

## Control Charts for Nonconformities (Defects)

- *So, nonconformities are acceptable to a level, not more!*
- *It is possible to develop control charts for either the **total number of nonconformities** in a unit or **the average number of nonconformities** per unit.*
- *These control charts usually assume that the occurrence of nonconformities in samples of constant size is well modeled by the **Poisson distribution**.*

## Control Charts for Nonconformities (Defects)

- *Consider the occurrence of nonconformities in an inspection unit of product occurs according to the Poisson distribution:*

$$p(x) = \frac{e^{-c} c^x}{x!} \quad x = 0, 1, 2, \dots$$

- *We recall that both the mean and variance of the Poisson distribution are the parameter  $c$ .*

## *c* chart (Nonconformities)

- Therefore, a **control chart for nonconformities** (or defects), or **c chart** with three-sigma limits would be defined as follows

### Control Chart for Nonconformities: Standard Given

$$\begin{aligned} \text{UCL} &= c + 3\sqrt{c} \\ \text{Center line} &= c \\ \text{LCL} &= c - 3\sqrt{c} \end{aligned} \quad (7.16)$$

## *c* chart (Nonconformities)

- If no standard is given, then  $c$  may be estimated as the observed average number of nonconformities in a preliminary sample of inspection units

### Control Chart for Nonconformities: No Standard Given

$$\begin{aligned} \text{UCL} &= \bar{c} + 3\sqrt{\bar{c}} \\ \text{Center line} &= \bar{c} \\ \text{LCL} &= \bar{c} - 3\sqrt{\bar{c}} \end{aligned} \quad (7.17)$$

## *c* chart (Nonconformities)

- *Example 7.3* Table 7.7 presents the number of nonconformities observed in 26 successive samples of 100 printed circuit boards. Set up a *c* chart for these data.

■ TABLE 7.7

Data on the Number of Nonconformities in Samples of 100 Printed Circuit Boards

Sample Number	Number of Nonconformities	Sample Number	Number of Nonconformities
1	21	14	19
2	24	15	10
3	16	16	17
4	12	17	13
5	15	18	22
6	5	19	18
7	28	20	39
8	20	21	30
9	31	22	24
10	25	23	16
11	20	24	19
12	24	25	17
13	16	26	15

## *c* chart (Nonconformities)

- *Answer.* Since the 26 samples contain 516 total nonconformities, we estimate *c* by


$$\bar{c} = \frac{516}{26} = 19.85$$

$$UCL = \bar{c} + 3\sqrt{\bar{c}} = 19.85 + 3\sqrt{19.85} = 33.22$$

$$\text{Center line} = \bar{c} = 19.85$$

$$LCL = \bar{c} - 3\sqrt{\bar{c}} = 19.85 - 3\sqrt{19.85} = 6.48$$

Two points plot outside the control limits:  
samples 6 and 20.



## *u chart (Nonconformities per unit)*

- *We would often prefer to use several inspection units in the sample, thereby increasing the area of opportunity for the occurrence of nonconformities.*
- *Sample size should be selected according to the statistical considerations and may vary each time*
- *If we find  $x$  total nonconformities in a sample of  $n$  inspection units, then the average number of nonconformities per inspection unit is*

$$u = \frac{x}{n}$$

- *Note that  $x$  is a Poisson random variable*

## *u chart (Nonconformities per unit)*

- *The parameters of the control chart for the average number of nonconformities per unit are as follows*

### **Control Chart for Average Number of Nonconformities per Unit**

$$UCL = \bar{u} + 3\sqrt{\frac{\bar{u}}{n}}$$

$$\text{Center line} = \bar{u}$$

$$LCL = \bar{u} - 3\sqrt{\frac{\bar{u}}{n}}$$

(7.19)

## *u chart (Nonconformities per unit)*

- *Example 7.4 Draw a u chart for the following data:*

$$\bar{u} = \frac{\sum_{i=1}^{20} u_i}{20} = \frac{1.48}{20} = 0.0740$$

$$UCL = \bar{u} + 3\sqrt{\frac{\bar{u}}{n}} = 0.0740 + 3\sqrt{\frac{0.0740}{50}} = 0.1894$$

$$\text{Center line} = \bar{u} = 1.93$$

$$LCL = \bar{u} - 3\sqrt{\frac{\bar{u}}{n}} = 0.0740 - 3\sqrt{\frac{0.0740}{50}} = -0.0414$$

Data on Number of Shipping Errors in a Supply Chain Network

Sample Number (week), $i$	Sample Size, $n$	Total Number of Errors (Nonconformities), $x_i$	Average Number of Errors (Nonconformities) per Unit, $u_i = x_i/n$
1	50	2	0.04
2	50	3	0.06
3	50	8	0.16
4	50	1	0.02
5	50	1	0.02
6	50	4	0.08
7	50	1	0.02
8	50	4	0.08
9	50	5	0.10
10	50	1	0.02
11	50	8	0.16
12	50	2	0.04
13	50	4	0.08
14	50	3	0.06
15	50	4	0.08
16	50	1	0.02
17	50	8	0.16
18	50	3	0.06
19	50	7	0.14
20	50	4	0.08
		74	1.48

## *u chart (Nonconformities per unit)*


- *Example 7.4 Draw a u chart for the following data:*

$$\bar{u} = \frac{\sum_{i=1}^{20} u_i}{20} = \frac{1.48}{20} = 0.0740$$

$$UCL = \bar{u} + 3\sqrt{\frac{\bar{u}}{n}} = 0.0740 + 3\sqrt{\frac{0.0740}{50}} = 0.1894$$

$$\text{Center line} = \bar{u} = 1.93$$

$$LCL = \bar{u} - 3\sqrt{\frac{\bar{u}}{n}} = 0.0740 - 3\sqrt{\frac{0.0740}{50}} = -0.0414$$



## *Procedures with Variable Sample Size*

- *Use control limits based on an average sample size*

$$\bar{n} = \sum_{i=1}^m n_i / m$$

- *Use a standardized control chart (this is the preferred option)*  
*LCL = -3 and UCL = +3 and the center line at zero.*

$$Z_i = \frac{u_i - \bar{u}}{\sqrt{\frac{\bar{u}}{n_i}}}$$

## *Alternative Probability Models for Count Data*

- *Most applications of the **c chart** assume that the **Poisson distribution** is the correct probability model underlying the process.*
- *It is not the only distribution that could be utilized as a model of **count** or nonconformities per unit-type data*
- *Various types of phenomena can produce distributions of defects that are not well modeled by the Poisson distribution.*
  - *In the Poisson distribution, the mean and the variance are equal. When the sample data indicate that **the sample variance is substantially different from the mean**, the Poisson assumption is likely to be **inappropriate**.*

## Alternative Probability Models for Count Data

- Kaminsky et al. (1992) have proposed control charts for counts based on the **geometric distribution**.
- The probability model that they use for the geometric distribution is

$$p(x) = p(1 - p)^{x-a} \text{ for } x = a, a + 1, a + 2, \dots$$

where  $a$  is the known minimum possible number of events.

- The two statistics that can be used to form a control chart are
  - the **total** number of events  $T = x_1 + x_2 + \dots + x_n$
  - the **average** number of events  $\bar{x} = \frac{x_1 + x_2 + \dots + x_n}{n}$

## Alternative Probability Models for Count Data

- Suppose that the data from the process are available as a subgroup of size  $n$ , say  $x_1, x_2, \dots, x_n$
- These observations are **independently and identically distributed** observations from a **geometric distribution** when the process is stable (in control).
- We know that the sum of independently and identically distributed geometric random variables is a **negative binomial** random variable.

## *Alternative Probability Models for Count Data*

- The mean and variance of the **total** number of events  $T$  are

$$\mu_T = n \left( \frac{1-p}{p} + a \right) \qquad \sigma_T^2 = \frac{n(1-p)}{p^2}$$

- The mean and variance of the **average** number of events are

$$\mu_{\bar{x}} = \frac{1-p}{p} + a \qquad \sigma_{\bar{x}}^2 = \frac{1-p}{np^2}$$

## *Alternative Probability Models for Count Data*

- Kaminsky et al. (1992) refer to ...
- The control chart for the **total** number of events as a **g chart**
- The control chart for the **average** number of events as an **h chart**
- The center lines and control limits for each chart are shown in the following display.

## *g and h chart*

- The center lines and control limits for each chart are shown in the following display.

<b><i>g and h Control Charts, Standards Given</i></b>		
	Total number of events chart, <i>g</i> chart	Average number of events chart, <i>h</i> chart
Upper control limit (UCL)	$n\left(\frac{1-p}{p} + a\right) + L\sqrt{\frac{n(1-p)}{p^2}}$	$\frac{1-p}{p} + a + L\sqrt{\frac{1-p}{np^2}}$
Center line (CL)	$n\left(\frac{1-p}{p} + a\right)$	$\frac{1-p}{p} + a$
Lower control limit (LCL)	$n\left(\frac{1-p}{p} + a\right) - L\sqrt{\frac{n(1-p)}{p^2}}$	$\frac{1-p}{p} + a - L\sqrt{\frac{1-p}{np^2}}$

## *g and h chart*

- While we have assumed that ***a* is known**, in most situations the parameter ***p* will likely be unknown**.

<b><i>g and h Control Charts, No Standards Given</i></b>		
	Total number of events chart, <i>g</i> chart	Average number of events chart, <i>h</i> chart
Upper control limit (UCL)	$\bar{t} + L\sqrt{n\left(\frac{\bar{t}}{n} - a\right)\left(\frac{\bar{t}}{n} - a + 1\right)}$	$\frac{\bar{t}}{n} + \frac{L}{\sqrt{n}}\sqrt{\left(\frac{\bar{t}}{n} - a\right)\left(\frac{\bar{t}}{n} - a + 1\right)}$
Center line (CL)	$\bar{t}$	$\frac{\bar{t}}{n}$
Lower control limit (LCL)	$\bar{t} - L\sqrt{n\left(\frac{\bar{t}}{n} - a\right)\left(\frac{\bar{t}}{n} - a + 1\right)}$	$\frac{\bar{t}}{n} - \frac{L}{\sqrt{n}}\sqrt{\left(\frac{\bar{t}}{n} - a\right)\left(\frac{\bar{t}}{n} - a + 1\right)}$

## Demerit Systems

- *With complex products such as automobiles, computers, or major appliances, we usually find that many **different types of nonconformities** or defects can occur.*
- ***Not all** of these types of defects are **equally important***
- *A unit of product having one very serious defect would probably be classified as nonconforming to requirements, but a unit having several minor defects might not necessarily be nonconforming*
- *For example, we can classify nonconformities as either **functional defects** or **appearance defects** if a two-class system is preferred.*
- ***Demerit systems for attribute data** can be of value in these situations.*

## Demerit Systems

- *One possible demerit scheme is defined as follows*

**Class A Defects—Very Serious.** The unit is either completely unfit for service, or will fail in service in such a manner that cannot be easily corrected in the field, or will cause personal injury or property damage.

**Class B Defects—Serious.** The unit will possibly suffer a Class A operating failure, or will certainly cause somewhat less serious operating problems, or will certainly have reduced life or increased maintenance cost.

**Class C Defects—Moderately Serious.** The unit will possibly fail in service, or cause trouble that is less serious than operating failure, or possibly have reduced life or increased maintenance costs, or have a major defect in finish, appearance, or quality of work.

**Class D Defects—Minor.** The unit will not fail in service but has minor defects in finish, appearance, or quality of work.

## Demerit Systems

- Let  $c_{iA}$ ,  $c_{iB}$ ,  $c_{iC}$ , and  $c_{iD}$  represent the number of Class A, Class B, Class C, and Class D defects, respectively, in the  $i^{\text{th}}$  inspection unit
- We assume that **each class of defect is independent**, and the occurrence of defects in each class is well modeled by a **Poisson distribution**
- Then we define the number of **demerits** in the inspection unit as

$$d_i = 100c_{iA} + 50c_{iB} + 10c_{iC} + c_{iD}$$

- The demerit weights of Class A—100, Class B—50, Class C—10, and Class D—1 are used fairly widely in practice.
- However, any reasonable set of weights appropriate for a specific problem may also be used.

## Demerit Systems

- Suppose that a sample of  $n$  inspection units is used.
- Then the number of demerits per unit is

$$u_i = \frac{D}{n}$$

$$D = \sum_{i=1}^n d_i$$

$$d_i = 100c_{iA} + 50c_{iB} + 10c_{iC} + c_{iD}$$

## Demerit Systems

- Since  $u_i$  is a linear combination of independent Poisson random variables, the statistics  $u_i$  could be plotted on a control chart with the following parameters:

$$\begin{aligned} \text{UCL} &= \bar{u} + 3\hat{\sigma}_u \\ \text{Center line} &= \bar{u} \\ \text{LCL} &= \bar{u} - 3\hat{\sigma}_u \end{aligned} \quad (7.23)$$

where

$$\bar{u} = 100\bar{u}_A + 50\bar{u}_B + 10\bar{u}_C + \bar{u}_D \quad (7.24)$$

and

$$\hat{\sigma}_u = \left[ \frac{(100)^2 \bar{u}_A + (50)^2 \bar{u}_B + (10)^2 \bar{u}_C + \bar{u}_D}{n} \right]^{1/2} \quad (7.25)$$

## Control Charts for Attributes

	$p$ (fraction)	$np$ (number of nonconforming)	$c$ (count of nonconformances)	$u$ (count of nonconformances/unit)
CL	$\bar{p}$	$n\bar{p}$	$\bar{c}$	$\bar{u}$
UCL	$\bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$	$n\bar{p} + 3\sqrt{n\bar{p}(1-\bar{p})}$	$\bar{c} + 3\sqrt{\bar{c}}$	$\bar{u} + 3\sqrt{\frac{\bar{u}}{n}}$
LCL	$\bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$	$n\bar{p} - 3\sqrt{n\bar{p}(1-\bar{p})}$	$\bar{c} - 3\sqrt{\bar{c}}$	$\bar{u} - 3\sqrt{\frac{\bar{u}}{n}}$
Notes	If $n$ varies, use $\bar{n}$ or individual $n_i$	$n$ must be a constant	$n$ must be a constant	If $n$ varies, use $\bar{n}$ or individual $n_i$

## Control Charts for Attributes

Standardized Attributes Control Charts Suitable for Short Production Runs

Attribute	Target Value	Standard Deviation	Statistic to Plot on the Control Chart
$\hat{p}_i$	$\bar{p}$	$\sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$	$Z_i = \frac{\hat{p}_i - \bar{p}}{\sqrt{\bar{p}(1-\bar{p})}/n}$
$n\hat{p}_i$	$n\bar{p}$	$\sqrt{n\bar{p}(1-\bar{p})}$	$Z_i = \frac{n\hat{p}_i - n\bar{p}}{\sqrt{n\bar{p}(1-\bar{p})}}$
$c_i$	$\bar{c}$	$\sqrt{\bar{c}}$	$Z_i = \frac{c_i - \bar{c}}{\sqrt{\bar{c}}}$
$u_i$	$\bar{u}$	$\sqrt{\bar{u}/n}$	$Z_i = \frac{u_i - \bar{u}}{\sqrt{\bar{u}/n}}$

## The Quality Chronicle

	<i>Attribute</i>	<i>Variable</i>
<i>Input / Output</i>	<i>Attribute Sampling Plans</i>	<i>Variable Sampling Plans</i>
<i>Process</i>	<i>Attribute Control Charts</i>	<i>Variable Control Charts</i>